

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	180/400.ccis. and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:01
L2	1149	439/402,342,296.ccis.	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L3	183	"439".clas. and steering and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L4	445	l2 and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:27
L5	1	l3 and l4	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:28
L6	28	73/862.08,862.191,862.321,862.326.ccis. and solder\$3	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:41
L7	112	73/866.1.ccis. and (solder\$3 steering torque)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:48
L8	16	73/866.1.ccis. and (steering)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:49
L9	8	73/431.ccis. and (steering)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:49
L10	119	73/862.08,862.191,862.321,862.326.ccis. and steering	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 17:50
S75	1356	((wire adj harnes\$5) and solder\$3)	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 16:25
S76	62	(solder\$3 same (wire lead line pin)).clm. and S75	US- PGPUB; USPAT; USOCR	OR	ON	2008/08/14 16:25
S77	30	(solder\$3 same (wire lead line pin)).clm. and S75	US- PGPUB	OR	ON	2008/08/14 16:26
S78	15	(solder\$3 and (wire lead line pin) and (torsion torque) and (detect\$4 sens\$4 measur\$4 transduc\$4 meter\$3)).clm.	US- PGPUB	OR	ON	2008/08/14 16:53

S79	14	180/444.ccls. and solder\$3	US-PGPUB	OR	ON	2008/08/14 16:56
-----	----	-----------------------------	----------	----	----	---------------------

8/14/2008 6:38:23 PM

C:\Documents and Settings\ppatel2\My Documents\EAST\Workspaces\11136588.wsp